

inches

centimeters



1	28.75	05.13
2	14.38	11.25
3	14.38	11.25
4	14.38	11.25
5	14.38	11.25
6	14.38	11.25
7	14.38	11.25
8	14.38	11.25
9	14.38	11.25
10	14.38	11.25
11	14.38	11.25
12	14.38	11.25
13	14.38	11.25
14	14.38	11.25
15	14.38	11.25
16	14.38	11.25
17	14.38	11.25
18	14.38	11.25
19	14.38	11.25
20	14.38	11.25
21	14.38	11.25
22	14.38	11.25
23	14.38	11.25
24	14.38	11.25
25	14.38	11.25
26	14.38	11.25
27	14.38	11.25
28	14.38	11.25
29	14.38	11.25
30	14.38	11.25

1	39.37	09.91
2	19.69	04.95
3	13.13	03.30
4	09.85	02.45
5	07.88	02.00
6	06.70	01.70
7	05.90	01.50
8	05.28	01.35
9	04.80	01.25
10	04.42	01.18
11	04.12	01.13
12	03.88	01.09
13	03.69	01.06
14	03.53	01.03
15	03.40	01.01
16	03.29	00.99
17	03.20	00.98
18	03.12	00.97
19	03.05	00.96
20	03.00	00.96
21	02.95	00.95
22	02.91	00.95
23	02.87	00.95
24	02.84	00.95
25	02.81	00.95
26	02.78	00.95
27	02.75	00.95
28	02.72	00.95
29	02.70	00.95
30	02.68	00.95

1	39.37	09.91
2	19.69	04.95
3	13.13	03.30
4	09.85	02.45
5	07.88	02.00
6	06.70	01.70
7	05.90	01.50
8	05.28	01.35
9	04.80	01.25
10	04.42	01.18
11	04.12	01.13
12	03.88	01.09
13	03.69	01.06
14	03.53	01.03
15	03.40	01.01
16	03.29	00.99
17	03.20	00.98
18	03.12	00.97
19	03.05	00.96
20	03.00	00.96
21	02.95	00.95
22	02.91	00.95
23	02.87	00.95
24	02.84	00.95
25	02.81	00.95
26	02.78	00.95
27	02.75	00.95
28	02.72	00.95
29	02.70	00.95
30	02.68	00.95

1	39.37	09.91
2	19.69	04.95
3	13.13	03.30
4	09.85	02.45
5	07.88	02.00
6	06.70	01.70
7	05.90	01.50
8	05.28	01.35
9	04.80	01.25
10	04.42	01.18
11	04.12	01.13
12	03.88	01.09
13	03.69	01.06
14	03.53	01.03
15	03.40	01.01
16	03.29	00.99
17	03.20	00.98
18	03.12	00.97
19	03.05	00.96
20	03.00	00.96
21	02.95	00.95
22	02.91	00.95
23	02.87	00.95
24	02.84	00.95
25	02.81	00.95
26	02.78	00.95
27	02.75	00.95
28	02.72	00.95
29	02.70	00.95
30	02.68	00.95

D50 Illuminant, 2 degree observer

Don Williams

All values are batch averages

M000549